

RDP 1385-59
cy 4 of 5
3 March 1959

25X1A TO : [redacted]

SUBJECT: Flint Equipment Malfunction Report for February 1959

25X1A
Attachment C - Some interference was encountered between [redacted] equipments in aircraft 378. Corrective action is being taken but has not been completed as of this date.

25X1A
Attachment B - A regulated 150 volt supply failed in [redacted] equipment while on test flight. The supply was repaired and is now functioning properly.

25X1A [redacted]

Distribution:

Orig & 1 - Addressee
3 - O-15
4 - RI
5 - Carone

A.W.R./bs